



**BUILDING DEPARTMENT**

190 Malabar Road, S.E., Palm Bay, FL 32908  
Phone: (321) 953-8924 • Fax: (321) 953-8925

Permit Number: \_\_\_\_\_

**INSULATION CERTIFICATE**

TO: Palm Bay Building Division                      Subdivision: \_\_\_\_\_

Lot \_\_\_\_\_ Block \_\_\_\_\_ Unit \_\_\_\_\_ Parcel \_\_\_\_\_

SITE ADDRESS \_\_\_\_\_

The undersigned hereby certifies that insulation has been installed in the above described property to meet the minimum requirements for R-Value of the Florida Energy Efficiency Code, as follows:

1. Exterior CBS walls have been insulated with (select one at bottom) to a thickness of \_\_\_\_\_ inches, which thickness according to \_\_\_\_\_ will yield an "R" value \_\_\_\_\_ at bags per square feet.                      *MANUFACTURER*

- |                    |                  |                 |
|--------------------|------------------|-----------------|
| Spray on cellulose | Fiberglass Batts | Rock Wool Batts |
| Aluminum Foil      | Polystyrene      | Other           |

Exterior (Frame Walls) have been insulated with (select one at bottom) to thickness of \_\_\_\_\_ inches, which thickness, according to \_\_\_\_\_ will yield an "R" value \_\_\_\_\_ .                      *MANUFACTURER*

- |                    |                  |                 |
|--------------------|------------------|-----------------|
| Spray-on cellulose | Fiberglass Batts | Rock Wool Batts |
| Aluminum Foil      | Polyurethane     | Other           |

2. Ceiling (level) have been insulated with (select one at bottom) to a thickness of \_\_\_\_\_ inches, which thickness according to \_\_\_\_\_ will yield an "R" value \_\_\_\_\_ at bags per square feet.                      *MANUFACTURER*

- |                      |                       |                    |
|----------------------|-----------------------|--------------------|
| Fiberglass Blankets  | Fiberglass Loose Fill | Rock Wool Blankets |
| Rock Wool Loose Fill | Cellulose Loose Fill  | Other              |

Ceiling (Vaulted/Cathedral) have been insulated with (select one at bottom) to thickness of \_\_\_\_\_ inches, which thickness, according to \_\_\_\_\_ will yield an "R" value \_\_\_\_\_ .                      *MANUFACTURER*

- |                      |                       |                    |
|----------------------|-----------------------|--------------------|
| Fiberglass Blankets  | Fiberglass Loose Fill | Rock Wool Blankets |
| Rock Wool Loose Fill | Cellulose Loose Fill  | Other              |

3. Interior Knee Walls have been insulated with a Mineral Fiber Batt to a thickness of \_\_\_\_\_ inches, which thickness, according to \_\_\_\_\_ will yield an "R" value of \_\_\_\_\_ .  
*MANUFACTURER*

4. Garage Partition Walls of conditioned living area have been insulated to a thickness of \_\_\_\_\_ inches, which thickness, according to \_\_\_\_\_ will yield an "R" value of \_\_\_\_\_ .  
*MANUFACTURER*

5. The following areas have not been insulated: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

\_\_\_\_\_  
CONTRACTOR or OWNER/BUILDER

By: \_\_\_\_\_

Date: \_\_\_\_\_

\_\_\_\_\_  
INSULATION CONTRACTOR

By: \_\_\_\_\_

Date: \_\_\_\_\_